

Product Safety Recall



Pedal Pacer 2 MD

PDRDPC2SL50, PDRDPC2SL53, PDRDPC2SL56,
PDRDPC2SL59, PDRDPC2LB45, PDRDPC2LB48, PDRDPC2LB51

Sold at 99 Bikes between December 2020 and March 2021

- Defect** Potential defect in the front hub retention that may cause the front wheel to become dislodged from the front fork if the Quick Release Skewer is not properly tightened or secured.
- Hazard** If the defect occurs while someone is riding the bicycle, serious injury may occur.
- What to do** You should stop using the bicycle immediately and return it to us to have either a 'Theft Prevention' Nuted Axle installed or a replacement fork fitted should you wish to keep the Quick Release.
- Contact details** You can contact your nearest 99 Bikes store by phoning (07) 3739 8807 Mon-Fri: 8:00am - 7:00pm Sat-Sun: 8:30am - 4:00pm, via email at help@99bikes.com.au or go to www.99bikes.com.au

See productsafety.gov.au for
Australian product recall information